

## Anyone else having real issues with the new tires?

Posted by Timwold - 18 Mar 2013 20:57

---

This past weekend there were 7 Spec cars (SP1) on the new RR tires at TWS. All 7 of us had the tires delaminate, two of them severally. One had a "strip come off around the entire tire and another lost a "x " chunk. Most of the issues we the formation of a line in the tread but with the two described early we all stop using the tires and put on the RA1 tires. We felt it was a possible safety issue. The guy driving the car which lost part of the tread around the entire tire said the car was very difficult to handle. With the speeds at TWS it a prudent move to go back to the RA1. The issues were all reported before 5 heat cycles and all of the tires were on the cars correctly. It was in the mid 80's in College station.

I can report the RR is faster.

=====

## Re: Anyone else having real issues with the new tires?

Posted by Sterling Doc - 20 Mar 2013 19:26

---

My experience is that they will split if mounted incorrectly, and often after only 1 or two sessions, but if you find it, and put it in the proper place before that split opens up, they will seal back down.

I emailed with Toyo tonight, and they are working on getting the tires in question.

Double check the mounting, guys, it is critical - date codes on the left on the front axle, and on the right on the rear axle. The tire shop needs to mount two tires with the date codes out, and two with the date codes in to make this work.

=====

## Re: Anyone else having real issues with the new tires?

Posted by Timwold - 21 Mar 2013 06:25

---

I believe all 7 of had the tires mounted correctly and had them on the car correctly. I confirmed that mine were on the car correctly. All of the cars had the seperation at the line on the rear tires. The attached picture is what happened to Blazer's tire after 4 heat cycles. Steve lost the tread all the way around the tire in a "strip.

My tires were not as severe but after seeing those two tires we all decided to put the RA1s on and be

slower.

=====

**Re: Anyone else having real issues with the new tires?**

Posted by Sterling Doc - 21 Mar 2013 10:20

---

Tim, thanks for the picture. That looks very similar to what happened to my first set, before the mounting recommendations. I ran a 4.5 hour enduro, with probably more than an hour with a mild vibration that (in retrospect) was likely that flap missing. Can you confirm the location & orientation of that tire?

Do you have any pictures of your tires?

What I am most interested in at this time is if any tires *confirmed* mounted correctly have lost chunks of rubber like the picture, as that is something we had not seen yet, and would be important to know right away.

I'll keep in contact with Toyo on this.

=====

**Re: Anyone else having real issues with the new tires?**

Posted by Timwold - 21 Mar 2013 14:07

---

The tire that chunked was on the car correctly. It was a rear wheel.

My tires only have a slight separate (1mm or so) that did not go all the across the tire. I do not have any pictures on my tires.

The issues we experienced at TWS have already been reported to Toyo.

=====

**Re: Anyone else having real issues with the new tires?**

Posted by Sterling Doc - 21 Mar 2013 14:45

---

Tim, thanks again, and for following up with Toyo. The Toyo engineer I emailed was aware of this

situation. I will let you guys know when I know more.

=====